


THREE-PHASE, THREE-WIRE DELTA

Measurement of energy on a three-phase, three-wire Delta service with a 2-stator meter.

most economical method...




5-TERMINAL
NON-CIRCUIT
CLOSING SOCKET


1

3

LOAD



FORM 12S



D5S-5 METER
INTERNAL DIAGRAM
FRONT VIEW