


THREE-PHASE, FOUR-WIRE WYE

Measurement of energy on a three-phase, four-wire Wye service with two matched ratio CT's and a 2-stator meter.

most economical method...



8-TERMINAL
CIRCUIT
CLOSING
SOCKET
FRONT
VIEW

FRONT VIEW
FORM 5S

D5S-2 METER
INTERNAL DIAGRAM

THE REGISTER MULTIPLIER EQUALS THE CT RATIO
FOR SECONDARY-RATED METERS