


THREE-PHASE, FOUR-WIRE WYE

Measurement of energy on a three-phase, four-wire Wye service with 3 CT's (Delta connected secondaries) and a 2-stator meter.

alternate economical method...



THE REGISTER MULTIPLIER EQUALS THE CT RATIO
FOR SECONDARY-RATED METERS