


THREE-PHASE, FOUR-WIRE WYE

Measurement of energy on a three-phase, four-wire Wye service with 3 CT's and a 3-stator meter.

alternate conventional method...



THE REGISTER MULTIPLIER EQUALS THE CT RATIO
FOR SECONDARY-RATED METERS